



VOLKSWAGEN TRANSPORTER: 1RNT590

Vinnumber:	WV1ZZZ7HZHH054322	Versionname:	
First Registrationdate:	5/10/2016	Fiscalpower:	
Expertise Mileage:	21073	Power Kw:	75
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2707
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 7 mm	Re.R.	Hankook: 7 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1096,46
-------------------	---------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	--------



Interior, Dirty, Cleaning	0,00
---------------------------	------





Trunk door R R, Dent(s), It - Spot repair 115,56



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rearlight L, Crack, E - Replace 91,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15

