



PEUGEOT 207: 1FLI760

Vinnumber:	VF3WE9HP0DE022256	Versionname:	207 SW Active FAP 92PK
First Registrationdate:	6/08/2013	Fiscalpower:	
Expertise Mileage:	102644	Power Kw:	68
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/88 H Steel			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1173,90
-------------------	----------------

Boot carpet, Worn, Acceptable	0,00
-------------------------------	-------------

No pictures to display

Front bumper, Deformed / Strained, Smart repair	110,64
---	---------------







Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
---	---------------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Backrest cover F L, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Full screen GPS, Not functioning (well), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Crack, E - Replace	413,76
	
Bonnet, Chemical pollution, LI - Repair and paint (complete)	232,06
	
Wheel cover R R, Scratch(es), E - Replace	24,00
	
Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical pollution, LI - Repair and paint (complete)	200,00
	
Wheel cover F R, Scratch(es), E - Replace	24,00
