



**RENAULT KADJAR: 1 SSB401**

Vinnnumber:	<b>VF1RFE00457039013</b>	Versionname:	<b>1.2 Energy TCe 130 EDC Bose Edition</b>
First Registrationdate:	<b>30/06/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>27239</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3831</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/40/19/93 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 1 mm</b>	Fr.R.	<b>Continental: 2 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1232,94</b>
--------------------------	----------------

<b>Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
--	--------------



<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>	<b>241,80</b>
--	---------------



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display


Door panel R L, Broken, E - Replace 114,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Bumper corner R L, Scratch(es), Smart repair 110,64



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display