


RENAULT Clio: 1GIA508

Vinnnumber:	VF15RJL0H50299289	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	13/02/2014	Fiscalpower:	
Expertise Mileage:	58173	Power Kw:	66
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2621
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	568,32
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56



Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Damaged, E - Replace	30,72



Wing R R, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Dent(s), PDR - Knock out without painting 63,00



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Roof pillar L, Dent(s), PDR - Knock out without painting 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Damaged, E - Replace 24,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Knock out without painting 102,60

