


**RENAULT ESPACE: 1FLM911**

Vinnumber:	<b>VF1JKFJC649428848</b>	Versionname:	<b>2.0 Dsl 110KW</b>
First Registrationdate:	<b>7/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>111152</b>	Power Kw:	
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>4714</b>
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Panoramic roof
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/101 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	788,64
-------------------	--------

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

*No pictures to display*

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair 110,64



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door trim R R, Scratch(es), E - Replace 54,00



Wing R L, Bad repair, Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display