



| | | | |
|----------------------------|--------------------------|--------------|----------------------------|
| SEAT Ibiza: 1FGZ368 | | | |
| Vinnumber: | VSSZZZ6JZER007989 | Versionname: | IBIZA ST Style 90PK |
| First Registrationdate: | 26/06/2013 | Fiscalpower: | |
| Expertise Mileage: | 69250 | Power Kw: | 66 |
| Bodytype: | Break | Body color | Black |
| Gearbox: | MAN 5 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Steel |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 3510 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Steel | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

| | |
|-------------------------|-------------------------------|
| Options | |
| Radio CD | Luggage cover |
| Windows electric F | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |










| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|-----------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| Summer tyres: | 185/60/15/88 H Steel | | | |
| | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

| | | | |
|--|------------|------|----------------|
| Assistance equipment | | | |
| Spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 2403,72 |
| Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | | | 318,35 |



| | |
|--|--------------|
| Wheel cover R R, Scratch(es), E - Replace | 30,00 |
|--|--------------|

| | | |
|--|---|--------|
|  | Roof, Chemical polution, LI - Repair and paint (complete) | 481,50 |
|  | Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|  | Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|  | Wing R R, Chemical polution, LI - Repair and paint (complete) | 308,20 |
|  | Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|  | Door F R, Dent(s), PDR - Knock out without painting | 63,00 |
|  | Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|  | Wheel cover F L, Scratch(es), E - Replace | 30,00 |
|  | Door F L, Scratch(es), Acceptable | 0,00 |
| No pictures to display | | |
| | Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |



Door panel F L, Hole, Smart repair 110,64

