




RENAULT Scenic: 1EZL395			
Vinnnumber:	VF1JZ14K649041583	Versionname:	SCENIC PriviEge 110PK
First Registrationdate:	29/04/2013	Fiscalpower:	
Expertise Mileage:	78291	Power Kw:	81
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3206
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			805,00
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Bonnet, Bad repair, Acceptable	0,00
---------------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Bad repair, Acceptable 0,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bad repair, Acceptable 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), Acceptable 0,00

No pictures to display