



VOLKSWAGEN PASSAT VARIANT: 1LBP587

Vinnnumber:	WVWZZZ3CZGE043789	Versionname:	2.0 TDI VARIANT HIGHLINE
First Registrationdate:	12/08/2015	Fiscalpower:	
Expertise Mileage:	136490	Power Kw:	110
Bodytype:	Break	Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Blue
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	2625
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats F L ventilated	
GPS storage		Seats F R ventilated	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunction		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/17/94 V LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	694,84
Bumper moulding F R, Broken, E - Replace	14,40



Door F L, Dent(s), PDR - Knock out without painting	63,00
------------------------------------------------------------	--------------



Bonnet, Bad repair, LI - Repair and paint (complete) 290,08



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), Acceptable 0,00

