


**SKODA Superb: 1HGF143**

Vinnnumber:	<b>TMBAJ73T1F9010038</b>	Versionname:	<b>SUPERB BER GreenLine Elegance 105PK</b>
First Registrationdate:	<b>14/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>86828</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3604</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	150,00
-------------------	--------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Door R L, Bad repair, Acceptable	0,00
----------------------------------	------



Door R R, Bad repair, Acceptable	0,00
----------------------------------	------



Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wing R R, Bad repair, Acceptable	0,00

