



SKODA Octavia: 1GGS791

Vinnnumber:	TMBJG7NE4E0119271	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	4/02/2014	Fiscalpower:	105PK
Expertise Mileage:	77853	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3112
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT **411,80**

Wing R L, Bad repair, Acceptable **0,00**



Bumper R, Scratch(es), LI - Repair and paint (complete) **211,80**



Wheel cover F R, Scratch(es), E - Replace 30,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Bad repair, Acceptable 0,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Reflector, Crack, E - Replace 20,00



Ignition key, Missing, E - Replace 150,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display