



RENAULT Grand Scenic: 1GMQ970

Vinnnumber:	VF1JZNAB650388095	Versionname:	GRAND SCENIC Energy Intens 7pl.130PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	87521	Power Kw:	96
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	25000 KM	Parking lot:	2603
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather and alcantara		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Emergency spare wheel	Yes		

Total cost ex VAT	990,68
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display
 Allowance F.L. Scratch(es), LI - Repair and paint (complete) 05,00

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Door F L, Scratch(es), Acceptable 0,00

No pictures to display

SD card, Missing, E - Replace 275,00



Protection plate M, Tear, E - Replace 74,00



Registration Document, Missing, E - Replace 150,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display