



## TOYOTA GT86: 1HLY990

Vinnnumber:	<b>JF1ZN6L72FG019145</b>	Versionname:	<b>GT86 COU Sport 200PK Aut.</b>
First Registrationdate:	<b>25/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>59915</b>	Power Kw:	<b>147</b>
Bodytype:		Body color	<b>Orange</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1122</b>
Number of doors	<b>2</b>		
Number of seats	<b>4</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather and alcantara</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
		Jack	<b>Yes</b>

Total cost ex VAT	380,00
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bad repair, Acceptable	0,00



Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

