



| VOLKSWAGEN Golf: 1HNG464           |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                        | <b>WVWZZZAUZFP512760</b> | Versionname: | <b>GOLF VAR Trendline 105PK</b> |
| First Registrationdate:            | <b>27/08/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>83561</b>             | Power Kw:    | <b>77</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Blue</b>                |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1208</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Steel</b>             |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

| Options                        |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting:          | <b>Headlighting Halogen</b>  |
| Type of GPS:                   | <b>GPS big screen color</b>  |
| Type of Lining:                | <b>Lining fabrics</b>        |
| Type of climate control:       | <b>Autom climate control</b> |
| Adaptive cruise control        |                              |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                             |                          |       |                          |
|----------------|-----------------------------|--------------------------|-------|--------------------------|
|                | <b>195/65/15/91 H Steel</b> |                          |       |                          |
| Summer tyres:  | Fr.L.                       | <b>Continental: 6 mm</b> | Fr.R. | <b>Continental: 6 mm</b> |
|                | Re.L.                       | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

| Assistance equipment                 |                            |
|--------------------------------------|----------------------------|
| Emergency spare wheel                | <b>Yes</b> Jack <b>Yes</b> |
| Total cost ex VAT                    | 400,00                     |
| Wing R L, Scratch(es), Acceptable    | 0,00                       |
| <i>No pictures to display</i>        |                            |
| Rear wiper arm, Damaged, E - Replace | 30,00                      |



|                                   |      |
|-----------------------------------|------|
| Wing R R, Dent(s), Acceptable     | 0,00 |
| <i>No pictures to display</i>     |      |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00

