



VOLVO XC60: 1KXU572

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | YV1DZARC1G2789227 | Versionname: | 2.0 D3 2WD MOMENTUM |
| First Registrationdate: | 28/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 138712 | Power Kw: | 110 |
| Bodytype: | SUV | Body color: | Beige |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2332 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Windows electric R | Rear parking sensors | |
| Cruise Control | Type of Tow bar | Tow bar removable |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|----------------------|-------|----------------------|
| | 235/65/17/108 V LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Pirelli: 3 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | | | |
|---------------------------------------|------------|------------|-------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 0,00 |
| Sill outer L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), Acceptable | | | 0,00 |

No pictures to display