



VOLVO V70: 1ERW869			
Vinnnumber:	YV1BW31A0D1270696	Versionname:	V70 D3 Kinetic St/St Geartr.136PK Aut.
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	164709	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3823
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/98 H LightMetal			
Summer tyres:	Fr.L.	Continental: 8 mm	Fr.R.	Continental: 8 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1197,00
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 288,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



