



VOLKSWAGEN PASSAT VARIANT: 1KSE035

Vinnumber:	WVWZZZ3CZGE006720	Versionname:	1.6 TDI VARIANT COMFORTLINE
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	137814	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4816
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1797,96
-------------------	----------------

Wing F L, Dent(s), PDR - Knock out without painting	63,00
---	--------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	---------------



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door frame R R, Dent(s), It - Spot repair 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80




Wing F R, Chemical polution, LI - Repair and paint (complete) 220,18



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Hole, Smart repair 110,64

