



**VOLVO V40: 1GJU122**

|                                    |                          |              |                          |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber:                        | <b>YV1MV8481E2141547</b> | Versionname: | <b>V40 D2 Base 115PK</b> |
| First Registrationdate:            | <b>26/02/2014</b>        | Fiscalpower: |                          |
| Expertise Mileage:                 | <b>168657</b>            | Power Kw:    | <b>84</b>                |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>         |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3208</b>              |
| Number of doors:                   | <b>5</b>                 |              |                          |
| Number of seats:                   | <b>5</b>                 |              |                          |
| Number head rests:                 | <b>5</b>                 |              |                          |
| Rims summer:                       | <b>Aluminium</b>         |              |                          |
| Category:                          | <b>Passenger Car</b>     |              |                          |
| Oil level:                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                          |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>211,80</b> |
|-------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|                                   |             |
|-----------------------------------|-------------|
| Bonnet, Stone chip(s), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|   |               |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |
|---|---------------|

