


FORD Mondeo: 1FMY118

| | | | |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber: | WF0GXXGBBGDP13820 | Versionname: | MONDEO CLIP Econetic Titanium 115PK |
| First Registrationdate: | 23/08/2013 | Fiscalpower: | |
| Expertise Mileage: | 118282 | Power Kw: | 85 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2714 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/55/16/97 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Uniroyal: 9 mm | Fr.R. | Uniroyal: 9 mm |
| | Re.L. | Uniroyal: 6 mm | Re.R. | Uniroyal: 6 mm |

Assistance equipment

| | | | |
|--|------------|------------|-------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 0,00 |
| Alloy rim F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Rearview mirror housing L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Seat cover F L, Worn, Acceptable | | | 0,00 |



| | | | |
|---------------------------------------|--|--|-------------|
| Tailgate, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), Acceptable | | | 0,00 |

| | |
|---|-------------|
| Bumper corner R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |