



BMW 3: 1DNR267

Vinnumber:	WBA3D11040F324973	Versionname:	3 BER 318d 136PK
First Registrationdate:	2/07/2012	Fiscalpower:	
Expertise Mileage:	67298	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 29000KM	Parking lot:	4711
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3163,68
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------

Wing R L, Scratch(es), LI - Repair and paint (complete) 300,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover R L, Dirty, Cleaning 25,00



Tailgate, Scratch(es), Acceptable 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Engine protective plate, Hole, E - Replace 69,00



Grill frame, Broken, E - Replace 54,00



Headlight L, Scratch(es), E - Replace 396,00



Wing R R, Dent(s), Acceptable 0,00





Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35



Bonnet, Chemical polution, 67 - Polish 0,00



Wing F R, Dent(s), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50

