


AUDI A1: 1GDV503

Vinnnumber:	WAUZZZ8X9EB068082	Versionname:	A1 5B Attraction 90PK
First Registrationdate:	10/01/2014	Fiscalpower:	
Expertise Mileage:	120975	Power Kw:	66
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3115
Maintenance:	BINNEN 800KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/88 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	589,94
-------------------	--------

Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Boot cover, Missing, E - Replace 40,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F R, Stain, Cleaning 0,50

