



AUDI A6: 1PED075

Vinnumber:	WAUZZZ4G9GN111018	Versionname:	
First Registrationdate:	15/06/2016	Fiscalpower:	
Expertise Mileage:	82471	Power Kw:	110
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	634,88
-------------------	---------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Door R L, Bad repair, Acceptable	0,00
----------------------------------	-------------



Bumper moulding F R, Crack, E - Replace	17,28
---	--------------



Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Bad repair, Acceptable	0,00
----------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

