



AUDI A4 AVANT: 1KRH344

Vinnnumber:	WAUZZZ8K1FA141134	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	16/06/2015	Fiscalpower:	
Expertise Mileage:	143845	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 27000 KM	Parking lot:	1211
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 769,64

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), It - Spot repair 115,56



Tailgate, Dent(s), PDR - Knock out without painting 63,00



Windscreen, Stone chip(s), Acceptable 0,00



Roofrack, Scratch(es), Acceptable 0,00



Rear Panel Internal Lining, Scratch(es), Smart repair 110,64



Alloy rim F R, Scratch(es), Acceptable 0,00



Rear roof pillar covering R, Hole, Smart repair 110,64



Alloy rim F L, Scratch(es), Acceptable 0,00



Door R L, Dent(s), PDR - Knock out without painting 63,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

