



BMW 3: 1FHY795

Vinnumber:	WBA3K11010F825230	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	3/07/2013	Fiscalpower:	
Expertise Mileage:	144177	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1118,20
-------------------	----------------

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	-------------


No pictures to display	
------------------------	--

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------

Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Rear window, Scratch(es), E - Replace 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display