



<b>BMW 3: 1HUH510</b>			
Vinnumber:	<b>WBA3K11010F835384</b>	Versionname:	<b>3 TOURING 318d 136PK</b>
First Registrationdate:	<b>6/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>117516</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2224</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining artificial leather</b>
Type of climate control:	<b>Autom climate control</b>


<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/60/16/92 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>0,00</b>
<b>Bonnet, Bad repair, Acceptable</b>			<b>0,00</b>



<b>Bumper R, Dent(s) and scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------



Roof, Bad repair, Acceptable	0,00
------------------------------	------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

*No pictures to display*