



FORD S Max: 1FAN350			
Vinnnumber:	WF0SXXGBWSDP10798	Versionname:	S-MAX Econetic Titanium St&St DPF 115PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	132508	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1111
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1351,34
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Wing F R, Bad repair, Acceptable	0,00
----------------------------------	------




Rear window, Scratch(es), E - Replace 0,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Bad repair, Acceptable 0,00



Wing F R, Dent(s), LI - Repair and paint (complete) 264,21



Wing R R, Bad repair, Acceptable 0,00



Bumper R, Dent(s), Smart repair 110,64



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair 115,56



Door trim F R, Scratch(es), E - Replace 132,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

