



MERCEDES CLA: 1HPX041

Vinnnumber:	WDD1173121N133416	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	9/09/2014	Fiscalpower:	
Expertise Mileage:	120311	Power Kw:	80
Bodytype:	Coupé	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2315
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Type of Tow bar	No Tow bar
GPS storage			
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 6 mm	Re.R.	Yokohama: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	308,20
-------------------	---------------

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Seat cover F L, Tear, Acceptable	0,00
----------------------------------	-------------



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	