



**PEUGEOT 308: 1JAB197**

Vinnnumber:	<b>VF3LCBHXHES253027</b>	Versionname:	<b>308 SW BlueHDi Allure STT</b>
First Registrationdate:	<b>13/11/2014</b>	Fiscalpower:	<b>116PK</b>
Expertise Mileage:	<b>169311</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

**Degree of wear**

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 1990,78

Headlight L, Scratch(es), E - Replace 396,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Registration Document, Missing, E - Replace 150,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), Acceptable 0,00

*No pictures to display*

Certificate Of Conformity, Missing, E - Replace 150,00



Wing R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 268,18





Boot carpet, Damaged, E - Replace	25,00
-----------------------------------	-------

*No pictures to display*

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

