



**LEXUS CT: 1PAD674**

Vinnnumber:	<b>JTHKD5BH902274913</b>	Versionname:	<b>1.8 200H EXECUTIVE LINE</b>
First Registrationdate:	<b>19/05/2016</b>	Fiscalpower:	<b>AUTO</b>
Expertise Mileage:	<b>57533</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Burgundy</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2122</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>516,99</b>
-------------------	---------------

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Wing F L, Dent(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Door R L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00




Boot cover, Scratch(es), Smart repair 110,64



Wing F L, Scratch(es), Acceptable 0,00



Interior, Dirty, Cleaning 25,00



Rearview mirror basis R, Scratch(es), Acceptable 0,00

