



**FORD Transit 280M: 532BYP**

Vinnnumber:	<b>WF05XTTTF5AU54846</b>	Versionname:	<b>TRANSIT 280M B/F2C MWB Silverline 85PK</b>
First Registrationdate:	<b>18/08/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>195514</b>	Power Kw:	<b>63</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV26</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>6</b>		
Number head rests:	<b>6</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

- Radio CD
- Windows electric F
- Cruise Control
- Steering wheel multifunctional
- Type of headlighting **Headlighting Halogen**
- Type of GPS **No GPS**
- Type of Lining **Lining fabrics**
- Type of climate control **Manual climate control**

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/70/16/104 R Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>64,00</b>
-------------------	--------------

Door trim R L, Missing, E - Replace	<b>64,00</b>
-------------------------------------	--------------



Roof, Dent(s), Acceptable	<b>0,00</b>
---------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Trunk door R R, Dent(s) and scratch(es), Acceptable	<b>0,00</b>
---	-------------

No pictures to display

Sill outer L, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

No pictures to display

Bodywork, Not original part, Acceptable	<b>0,00</b>
---	-------------

No pictures to display

*No pictures to display*