



## MAZDA CX-5: 1FPI487

Vinnnumber:	<b>JMZKEF91600231562</b>	Versionname:	<b>CX-5 4x2 Active 150PK</b>
First Registrationdate:	<b>13/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>125393</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3118</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/65/17/102 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Yokohama: 3 mm</b>	Re.R.	<b>Yokohama: 3 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1054,80</b>
Wing R L, Chemical polution, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Interior, Stain, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Rearview mirror L complete, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R R, Bad repair, Paint			<b>0,00</b>



Door F R, Bad repair, Paint	0,00
-----------------------------	------



Bumper R, Dent(s) and scratch(es), Le - Replace and paint	766,80
---	--------



Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Rearview mirror R complete, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

*No pictures to display*

Door R L, Chemical polution, Acceptable	0,00
---	------

*No pictures to display*

Luggage space cover, Hole, E - Replace	288,00
--	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

