


PORSCHE Cayenne: AT7582

Vinnnumber:	WP1ZZZ92ZELA31908	Versionname:	CAYENNE Turbo D DPF Tiptr.S 245PK Aut.
First Registrationdate:	19/08/2013	Fiscalpower:	
Expertise Mileage:	72547	Power Kw:	180
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4307
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/55/18/109 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment










Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	2768,35
-------------------	---------

Wing F L, Chemical polution, LI - Repair and paint (complete)	264,21
---------------------------------------------------------------	--------



Wing R L, Chemical polution, LI - Repair and paint (complete)	369,84
---------------------------------------------------------------	--------

	Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
	Wing moulding F R, Scratch(es), E - Replace	96,00
	Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), Acceptable		
<i>No pictures to display</i>		
Wing R R, Chemical polution, LI - Repair and paint (complete)		
369,84		
	Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
		
	Reflector, Broken, E - Replace	40,00
	Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Wing trim R R, Scratch(es), E - Replace		
96,00		
	Roof, Chemical polution, LI - Repair and paint (complete)	577,80
	Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Wing F R, Chemical polution, LI - Repair and paint (complete)		
264,21		



Windscreen, Stone chip(s), Windscreen repair

88,20

