



**RENAULT Kangoo: 1EO0104**

Vinnumber:	<b>VF1KW25B548435496</b>	Versionname:	<b>KANGOO 2PLC Expression FAP 90PK</b>
First Registrationdate:	<b>7/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>168457</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3513</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Type of Tow bar <b>Tow bar fixed</b>
Cruise Control	
Steering wheel multifunctional	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining fabrics</b>	
Type of climate control <b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 1 mm</b>	Fr.R.	<b>Goodyear: 1 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	4853,04
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Interior, Dirty, Chemical cleaning	150,00
------------------------------------	--------



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror L complete, Broken, E - Replace 168,00



Wheel cover F R, Missing, E - Replace 30,00



Covering interior front pillar R, Scratch(es), Smart repair 110,64



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Ignition key, Missing, E - Replace 150,00

*No pictures to display*

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F L, Missing, E - Replace 30,00



Wheel cover R L, Missing, E - Replace 30,00



Seat cover F R, Hole, E - Replace 360,00



Bonnet, Scratch(es), Acceptable 0,00

*No pictures to display*

Dashboard, Scratch(es), E - Replace 690,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover R R, Missing, E - Replace 30,00



Bumper R, Scratch(es), Smart repair 110,64



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Luggage space cover, Missing, E - Replace 240,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



