



RENAULT Kangoo Express: 1CTN020

Vinnnumber:	VF1FW15B546838991	Versionname:	KANGOO Expr. B/F PLC Gr.Conf.(EU5)90PK
First Registrationdate:	24/02/2012	Fiscalpower:	
Expertise Mileage:	110889	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3704
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1249,40
-------------------	---------

Bodywork, Not original part, Remove lettering	0,00
---	------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	------





Steel rim F L, Scratch(es), Acceptable	0,00
--	------





Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------


No pictures to display

Headlight L, Crack, E - Replace	321,00
	


Door F R, Dent(s), PDR - Knock out without painting	63,00
	

Windscreen, Crack, E - Replace	395,40
	


Reversible boot mat, Tear, Acceptable	0,00
	

Rearview mirror basis L, Broken, E - Replace	149,00
	


Bumper R, Dent(s), Acceptable	0,00
No pictures to display	

Headlight R, Crack, E - Replace	321,00
	

Steel rim R L, Scratch(es), Acceptable	0,00
	

Seat cover F L, Worn, Acceptable	0,00
	

Steel rim R R, Scratch(es), Acceptable	0,00
	

Roof, Dent(s), Acceptable	0,00
	

No pictures to display

Steel rim F R, Scratch(es), Acceptable

0,00

