


**SKODA Octavia: 1HCE816**

Vinnumber:	<b>TMBJG9NE7F0009991</b>	Versionname:	<b>OCTAVIA COMBI Ambition</b>
First Registrationdate:	<b>17/06/2014</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>136574</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1206</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>3722,57</b>
-------------------	----------------

Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>
---	---------------



Door F L, Dent(s) and scratch(es), Le - Replace and paint	<b>1082,52</b>
---	----------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Outer door handle F L, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Dent(s) and scratch(es), LI - Repair and paint (complete) 115,56





Door frame R L, Dent(s), It - Spot repair 115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s) and scratch(es), Le - Replace and paint 530,02



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display