



## SKODA Octavia: 1FOH417

Vinnnumber:	<b>TMBJG7NE6E0048851</b>	Versionname:	<b>OCTAVIA COMBI Ambition</b>
First Registrationdate:	<b>5/09/2013</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>118363</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>4810</b>
Maintenance:	<b>ONDERHOUD NODIG</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>No Tow bar</b>
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>
------------	------------

Total cost ex VAT	350,00
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper cover R M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Hail damage, PDR - Hail	50,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 300,00



Maintenance, Maintenance, Execute 0,00

No pictures to display