



RENAULT MEGANE GRANDTOUR: 1JAB436

Vinnumber:	VF1KZ0R0251471114	Versionname:	1.5 DCI 95 TOMTOM? EDITION
First Registrationdate:	13/11/2014	Fiscalpower:	
Expertise Mileage:	177112	Power Kw:	70
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 20 DAGEN	Parking lot:	3333
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T Steel			
Winter tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	450,60
-------------------	--------

Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Maintenance book, Missing, E - Replace	0,00
--	------




Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Wheel cover F R, Broken, E - Replace 30,00



Bonnet, Dent(s), PDR - Knock out without painting 102,60



Windscreen, Stone chip(s), E - Replace 138,00



Bumper corner R L, Scratch(es), LI - Repair and paint (complete) 75,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper cover R M, Scratch(es), LI - Repair and paint (complete) 75,00

