



SKODA Superb: 1ERM209			
Vinnumber:	TMBJJ73T1D9043554	Versionname:	SUPERB COMBI GreenLin.Ambition DPF 105PK
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	75726	Power Kw:	77
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2433
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	221,00
Bumper F L, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Knock out without painting	63,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	

Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance book, Missing, P - Check	0,00
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Mats, Hole, Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), PDR - Knock out without painting	63,00
	
Tyre F R, Flat, Acceptable	0,00
	