



## VOLKSWAGEN Touran: 1GTH836

Vinnumber:	<b>WVGZZZ1TZEW090180</b>	Versionname:	<b>TOURAN Trendline BMT St&amp;St 7pl.105PK</b>
First Registrationdate:	<b>24/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>118472</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2328</b>
Maintenance:	<b>SERVICE IN 12500KM 157D</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>No Tow bar</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 1814,82

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Backrest cover R M, Scratch(es), Smart repair 64,32




Backrest cover R L, Scratch(es), Smart repair

64,32



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R R, Broken, E - Replace

30,00



Internal Boot Lining L, Scratch(es), Smart repair

110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wheel cover F R, Scratch(es), E - Replace


30,00



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Smart repair	110,64



Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Backrest cover R R, Scratch(es), Smart repair	64,32
---	-------



Trunk lid covering R, Scratch(es), E - Replace	247,10
--	--------



Wheel cover R L, Broken, E - Replace	30,00
--------------------------------------	-------

