


SKODA OCTAVIA COMBI: 1LBD581

Vinnnumber:	TMBJG7NE5F0089876	Versionname:	1.6 CRTDI 77KW GREENTEC AMBITION
First Registrationdate:	7/08/2015	Fiscalpower:	
Expertise Mileage:	135683	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2104
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2,5 mm	Fr.R.	Bridgestone: 2,5 mm
	Re.L.	Continental: 1,6 mm	Re.R.	Continental: 1,6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	257,00
-------------------	--------

Protection plate M, Tear, E - Replace	57,00
---------------------------------------	-------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	0,00
--	------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display