



VOLKSWAGEN MULTIVAN: 1NEV332

Vinnnumber:	WV2ZZZ7HZGH076106	Versionname:	2.0 CRTDI SCR 110KW BMT HIGHLINE 4WD MSQ
First Registrationdate:	8/02/2016	Fiscalpower:	
Expertise Mileage:	153504	Power Kw:	110
Bodytype:	Minibus	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3503
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Type of Tow bar	Tow bar removable
GPS storage			
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/92 W LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1665,80
Wing R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Internal Boot Lining R, Tear, Smart repair			110,64



Luggage space cover, Missing, E - Replace			180,00
---	--	--	---------------



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Knock out without painting 82,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), PDR - Knock out without painting 102,60



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Broken, Le - Replace and paint 506,25



Roof, Dent(s), PDR - Knock out without painting 63,00



Tailgate, Dent(s), PDR - Knock out without painting 102,60



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 286,76



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display