



VOLKSWAGEN Up: 1FLB144

Vinnnumber:	WVWZZAAZED014034	Versionname:	UP BER Move up 60PK
First Registrationdate:	2/08/2013	Fiscalpower:	
Expertise Mileage:	121114	Power Kw:	44
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3714
Number of doors:	5		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS portable
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	165/70/14/81 T Steel			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Total cost ex VAT	278,68
Tailgate, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), LI - Repair and paint (complete)	254,68



Wheel cover R L, Broken. E - Replace 24.00



Wing F R, Bad repair, Acceptable 0,00

