



VOLKSWAGEN Touran: 1GED578

Vinnnumber:	WVGZZZ1TZEW053644	Versionname:	TOURAN Highline BMT
First Registrationdate:	14/01/2014	Fiscalpower:	Start/Stop 105PK
Expertise Mileage:	124790	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3605
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 292,56

Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Knock out without painting 63,00



Door panel R L, Scratch(es), E - Replace 114,00



Step R, Bump, It - Spot repair 0,00



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Door trim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display