



VOLKSWAGEN Passat: 1HNC720			
Vinnnumber:	WVWZZZ3CZFE011664	Versionname:	PASSAT VAR Trendline BM 105PK
First Registrationdate:	26/08/2014	Fiscalpower:	
Expertise Mileage:	93244	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2129
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	858,61
Wheel cover R R, Scratch(es), Acceptable	0,00



Door F L, Chemical polution, LI - Repair and paint (complete)	318,35
---	---------------



Door panel F L, Worn, Acceptable	0,00
----------------------------------	------



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	--------



Roof pillar L, Chemical pollution, LI - Repair and paint (complete)	220,18
---	--------

