



**VOLKSWAGEN Golf: 1GTA521**

Vinnnumber:	<b>WVWZZZAUZEW372674</b>	Versionname:	<b>GOLF BER Trendline 122PK</b>
First Registrationdate:	<b>22/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>34050</b>	Power Kw:	<b>90</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>UITVOEREN</b>	Parking lot:	<b>4701</b>
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	2601,29
-------------------	---------

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Interior, Stain, Acceptable

0,00



Door F R, Bad repair, LI - Repair and paint (complete)

318,35



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Bad repair, LI - Repair and paint (complete)

308,20



Maintenance, Maintenance, Execute

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35





Wheel cover R L, Missing, E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Dent(s), PDR - Knock out without painting 159,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

