



VOLVO V40: 1HRT441

| | | | |
|-----------------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber: | YV1MV8481F2194030 | Versionname: | V40 D2 Base 115PK |
| First Registrationdate: | 16/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 79936 | Power Kw: | 84 |
| Bodytype: | | Body color | Gold |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 3809 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|-------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Windows electric R | Rear parking sensors | |
| Cruise Control | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/55/16/91 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 575,08 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

