



OPEL ZAFIRA: 1AGW931

Vinnumber:	W0LOAHM75B2056291	Versionname:	
First Registrationdate:	6/01/2011	Fiscalpower:	
Expertise Mileage:	125501	Power Kw:	
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4403
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	4657,04
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68



Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Rear window, Scratch(es), E - Replace 370,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





Wing R R, Dent(s) and scratch(es), Le - Replace and paint	1231,51
---	---------



Roof, Scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	414,35
---	--------



Rearview mirror housing R, Scratch(es), E - Replace	84,00
---	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display