



VOLKSWAGEN Polo: YD4147

Vinnumber:	WVWZZZ6RZFY105611	Versionname:	POLO BER Trendline BMT
First Registrationdate:	13/08/2014	Fiscalpower:	90PK
Expertise Mileage:	112230	Power Kw:	66
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3329
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Firestone: 7 mm	Re.R.	Firestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	178,80
-------------------	---------------

Door F L, Dent(s), PDR - Knock out without painting	82,80
---	--------------



Wheel cover F R, Missing, E - Replace	24,00
---------------------------------------	--------------



Wheel cover R L, Missing, E - Replace	24,00
---------------------------------------	--------------



Sill outer L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Missing, E - Replace	24,00



Wheel cover F L, Missing, E - Replace	24,00
---------------------------------------	-------



Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	