


VOLKSWAGEN GOLF : 1HFA529

Vinnumber:	WVWZZZAUZEP207380	Versionname:	
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	62441	Power Kw:	77
Bodytype:	Break	Body color	Light Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1306
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunction		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1915,80
Alloy rim F L, Damaged, LI - Repair and paint (complete)	95,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------





Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Rear wiper blade, Missing, E - Replace

30,00



Interior, Dirty, Cleaning

50,00



Bumper F, Damaged, LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------

