



BMW 3: LR5026

Vinnnumber:	WBA3L51060F810064	Versionname:	3 TOURING 330dAS 258PK Aut.
First Registrationdate:	12/09/2013	Fiscalpower:	
Expertise Mileage:	157500	Power Kw:	190
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3701
Maintenance:	IN 14000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/91 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm









Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	858,00
-------------------	---------------

Alloy rim F L polished, Scratch(es), E - Replace	235,20
--	---------------



	Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	Door F L, Dent(s), PDR - Knock out without painting	63,00
	Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	Bonnet, Dent(s), PDR - Knock out without painting	63,00
	Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		