


**FORD S Max: 1EZQ815**

Vinnnumber:	<b>WF0SXXGBWSDP16184</b>	Versionname:	<b>S-MAX Titanium DPF</b>
First Registrationdate:	<b>30/04/2013</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>178664</b>	Power Kw:	<b>100</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3401</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>6</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L
TV/DVD screen R		Seats electric F R
GPS storage	<b>HD</b>	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>255/50/17/98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 2 mm</b>	Fr.R.	<b>Bridgestone: 2 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Compressor	<b>Yes</b>
Repair kit	<b>Yes</b>		

**Total cost ex VAT** 895,11

**Tailgate, Scratch(es), Acceptable** 0,00

**Door R L, Scratch(es), LI - Repair and paint (complete)** 382,02



Door F L, Scratch(es), Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00



Bumper F M, Bad repair, LI - Repair and paint (partial) 115,00



Protection plate M, Tear, E - Replace 50,00



Bonnet, Rust, LI - Repair and paint (complete) 348,09



Maintenance book, Missing, E - Replace 0,00

No pictures to display